









PARTS INVENTORY		
ID	DESCRIPTION	QTY
A	Top 	1
B	Leg 1 	1
C	Leg 2 	2
D	M8 Washer 	12+1
E	M8Lock washer 	12+1
F	M8*30 Bolt 	12+1
G	Allen key for M8 	1



PS: Rotate all bolts to 80% first,
then rotate all bolts to 100%.

